



Two red-colored springs (p/n 10-320) are furnished with each Millionaire game, for use on the Right Eject Hole Assembly, *at the option of the operator.*

These springs are provided for use as replacements for the factory-installed spring (p/n 10-362), as indicated in the preceding diagram. They cause a slower eject action to occur, allowing the player a better opportunity to flip the ball, when it comes out of the Eject Hole.